

Assignment of Indicating Systems

Accessories Includes	Measuring amplifier	Software + PCI card	TDC sensor	Pressure transducer
CT 159.01 Electronic Indicating System for CT 159				
CT 159.03 Pressure Transducer and TDC Sensor for CT 150 / CT 152				
CT 159.04 Pressure Transducer and TDC Sensor for CT 151				
CT 159.05 Pressure Transducer and TDC Sensor for CT 153				
CT 100.13 Electronic Indicating System for CT 110				
CT 100.14 Pressure Transducer for CT 100.20				
CT 100.16 Pressure Transducer for CT 100.22				
CT 300.09 Electronic Indicating System for CT 300				
CT 300.16 Pressure Transducer and TDC Sensor for CT 300.03				2
CT 300.17 Pressure Transducer and TDC Sensor for CT 300.04				
CT 300.18 Pressure Transducer and TDC Sensor for CT 300.05				
CT 400.09 Electronic Indicating System for CT 400				
CT 400.16 Pressure Transducer and TDC Sensor for CT 400.01				
CT 400.17 Pressure Transducer and TDC Sensor for CT 400.02				